## Monthly Recall Report February, 2014 safer car.gov Division Heavy Truck & Bus Kev Word Veh. Type School Bus Models: Recall: Manufacturer: Vehicle Type: NHTSA Inv #: 14V043 2012 - 2014 CF Navistar, Inc. School Bus Subject: Influenced By: **Population:** Hybrid Transmission Software 22 MFR To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens. http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\_id=14V043&searchtype=quicksearch&summary=true Models: **Recall:** Manufacturer: Vehicle Type: NHTSA Inv #: 14V074 Daimler Trucks North America School Bus 2013 - 2015 MINOTOUR Subject: **Population: Influenced By:** Missing Floor Reinforcements for Seat Belts 287 MFR To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens. http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\_id=14V074&searchtype=quicksearch&summary=true Models: Recall: Manufacturer: Vehicle Type: NHTSA Inv #: 14V079 Daimler Trucks North America School Bus 2009 - 2015 SAF-T-LINER HDX Subject: **Population: Influenced By:** Ice May Form in Intake Manifold 727 MFR To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens. http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\_id=14V079&searchtype=quicksearch&summary=true Models: Manufacturer: Recall: Vehicle Type: NHTSA Inv #: 14V083 2009 - 2015 ALL AMERICAN Blue Bird Body Company School Bus Subject: **Population: Influenced By:** Ice May Form in Intake Manifold 715 MFR To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens. http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\_id=14V083&searchtype=quicksearch&summary=true Models: **Recall:** Manufacturer: Vehicle Type: NHTSA Inv #: 14V102 Starcraft Bus 2009 - 2010 PRODIGY School Bus EQ14-003 Subject: **Influenced By: Population:** 2009 - 2010 QUEST Electric Door Actuator May Lead to Fire 281 ODI To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens. http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl\_id=14V102&searchtype=quicksearch&summary=true