



# Monthly Recall Report July, 2013

|           |                   |          |
|-----------|-------------------|----------|
| Division  | Heavy Truck & Bus | Key Word |
| Veh. Type | School Bus        |          |

|   |                             |                |              |                |
|---|-----------------------------|----------------|--------------|----------------|
| Recall:   | Manufacturer:               | Vehicle Type:  | NHTSA Inv #: | Models:        |
| 13V306  | Matthews Specialty Vehicles | School Bus     |              | 2000 - 2000 FE |
| Subject:  | Population:                 | Influenced By: |              |                |
| Unexpected Unfurling of the Awning  | 5                           | MFR            |              |                |
| <p>To see a summary of the recall click the Link below.<br/>         To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p><a href="http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V306&amp;searchtype=quicksearch&amp;summary=true">http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V306&amp;searchtype=quicksearch&amp;summary=true</a></p> |                             |                |              |                |

|   |                |                |              |                                      |
|---|----------------|----------------|--------------|--------------------------------------|
| Recall:   | Manufacturer:  | Vehicle Type:  | NHTSA Inv #: | Models:                              |
| 13V320  | Navistar, Inc. | School Bus     |              | 2006 - 2012 CESB<br>2006 - 2013 RESB |
| Subject:  | Population:    | Influenced By: |              |                                      |
| Flip Seat/Possible Toe or Foot Pinch  | 662            | MFR            |              |                                      |
| <p>To see a summary of the recall click the Link below.<br/>         To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p><a href="http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V320&amp;searchtype=quicksearch&amp;summary=true">http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V320&amp;searchtype=quicksearch&amp;summary=true</a></p> |                |                |              |                                      |

|   |                        |                |              |  |
|---|------------------------|----------------|--------------|--|
| Recall:   | Manufacturer:          | Vehicle Type:  | NHTSA Inv #: | Models:  |
| 13V332  | Blue Bird Body Company | School Bus     |              | 2007 - 2014 ALL AMERICAN<br>2007 - 2014 VISION |
| Subject:  | Population:            | Influenced By: |              |  |
| Window Panel Adhesive Strength/FMVSS 221  | 172                    | MFR            |              |  |
| <p>To see a summary of the recall click the Link below.<br/>         To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p><a href="http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V332&amp;searchtype=quicksearch&amp;summary=true">http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V332&amp;searchtype=quicksearch&amp;summary=true</a></p> |                        |                |              |  |