



Monthly Recall Report

Nov 2011 Thru

Oct 2012

Division Heavy Truck & Bus

Key Word

Veh. Type School Bus

Recall: 11V569	Manufacturer: BLUE BIRD BODY COMPANY	Vehicle Type: School Bus	NHTSA Inv #:	Models: 2007 - 2012 ALL AMERICAN
Subject: FUEL LEAK	Population: 250	Influenced By: MFR		

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=11V569&searchtype=quicksearch&summary=true

Recall: 12V153	Manufacturer: BLUE BIRD BODY COMPANY	Vehicle Type: School Bus	NHTSA Inv #: PE11-030	Models: 2009 - 2011 ALL AMERICAN 2009 - 2011 MICRO BIRD 2009 - 2011 VISION
Subject: WHEELCHAIR LIFT/OUTER ROLL STOP LATCHING ME	Population: 125	Influenced By: ODI		

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V153&searchtype=quicksearch&summary=true

Recall: 12V217	Manufacturer: BLUE BIRD BODY COMPANY	Vehicle Type: School Bus	NHTSA Inv #:	Models: 2010 - 2013 ALL AMERICAN 2010 - 2013 VISION
Subject: CROSSED AIR BRAKE LINES/FMVSS 121	Population: 651	Influenced By: MFR		

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V217&searchtype=quicksearch&summary=true

Recall: 12V218	Manufacturer: BLUE BIRD BODY COMPANY	Vehicle Type: School Bus	NHTSA Inv #:	Models: 2010 - 2013 ALL AMERICAN 2010 - 2013 VISION
Subject: CROSSED AIR BRAKE LINES/FMVSS 121	Population: 31	Influenced By: MFR		

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V218&searchtype=quicksearch&summary=true

Recall: 12V261	Manufacturer: BLUE BIRD BODY COMPANY	Vehicle Type: School Bus	NHTSA Inv #:	Models: 2012 - 2013 ALL AMERICAN 2012 - 2013 VISION
Subject: ROOF ESCAPE HATCHES/FMVSS 217	Population: 1406	Influenced By: MFR		

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V261&searchtype=quicksearch&summary=true



Monthly Recall Report

Division	Heavy Truck & Bus	Key Word
Veh. Type	School Bus	

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V262	BLUE BIRD BODY COMPANY	School Bus	
Subject:	Population:	Influenced By:	
ROOF ESCAPE HATCHES/FMVSS 217	11	MFR	

Models:	
2012 - 2012	ALL AMERICAN
2012 - 2012	VISION

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V262&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V277	BLUE BIRD BODY COMPANY	School Bus	
Subject:	Population:	Influenced By:	
TREADLE VALVE PLUNGER	13	MFR	

Models:	
2013 - 2013	ALL AMERICAN

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V277&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V349	BLUE BIRD BODY COMPANY	School Bus	
Subject:	Population:	Influenced By:	
Hydraulic Brake Indicator Light	19	MFR	

Models:	
2013 - 2013	VISION

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V349&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V359	BLUE BIRD BODY COMPANY	School Bus	
Subject:	Population:	Influenced By:	
Mismatched Driver's Seat Belt Buckles	726	MFR	

Models:	
2013 - 2013	ALL AMERICAN
2013 - 2013	VISION

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V359&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V259	COLLINS BUS CORPORATION	School Bus	PE11-030
Subject:	Population:	Influenced By:	
WHEELCHAIR LIFT/OUTER ROLL STOP LATCHING ME	238	ODI	

Models:	
2008 - 2010	GRAND BANTAM
2008 - 2010	MID BUS GRAND GUIDE
2008 - 2010	MID BUS SUPER GUIDE
2008 - 2010	SUPER BANTAM

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V259&searchtype=quicksearch&summary=true



Monthly Recall Report

Division	Heavy Truck & Bus	Key Word
Veh. Type	School Bus	

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V340	COLLINS BUS CORPORATION	School Bus	
Subject:	Population:	Influenced By:	
Emergency egress windows/FMVSS 217	196	MFR	

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V340&searchtype=quicksearch&summary=true

2012 - 2012 DE
2012 - 2012 DH
2012 - 2012 SH
2012 - 2012 SL

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V342	COLLINS BUS CORPORATION	School Bus	
Subject:	Population:	Influenced By:	
Electrical Control Panel can fall	196	MFR	

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V342&searchtype=quicksearch&summary=true

2012 - 2012 DE
2012 - 2012 DH
2012 - 2012 SH
2012 - 2012 SL

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V345	COLLINS BUS CORPORATION	School Bus	
Subject:	Population:	Influenced By:	
Seat Bolt Fuel Filler Interference	116	MFR	

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V345&searchtype=quicksearch&summary=true

2012 - 2012 DH400
2012 - 2012 DH416
2012 - 2012 DH500
2012 - 2012 DH516
2012 - 2012 SH400
2012 - 2012 SL400

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V346	COLLINS BUS CORPORATION	School Bus	
Subject:	Population:	Influenced By:	
Double Out Door Hardware/drawstrings could catch	171	MFR	

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V346&searchtype=quicksearch&summary=true

2012 - 2012 DE
2012 - 2012 DH
2012 - 2012 SH
2012 - 2012 SL

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V386	COLLINS BUS CORPORATION	School Bus	
Subject:	Population:	Influenced By:	
Body Mount Bolts	317	MFR	

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V386&searchtype=quicksearch&summary=true

2012 - 2012 DE
2012 - 2012 DH
2012 - 2012 SH
2012 - 2012 SL



Monthly Recall Report

Division	Heavy Truck & Bus	Key Word
Veh. Type	School Bus	

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V387	COLLINS BUS CORPORATION	School Bus	
Subject:	Population:	Influenced By:	
Brake Line Position	282	MFR	

Models:
2012 - 2012 DE
2012 - 2012 DH
2012 - 2012 SH
2012 - 2012 SL

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V387&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
11V596	CORP. MICRO BIRD, INC.	School Bus	
Subject:	Population:	Influenced By:	
FMVSS 221/METAL CEILING PANELS	1227	MFR	

Models:
2009 - 2012 G5

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=11V596&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
11V597	CORP. MICRO BIRD, INC.	School Bus	
Subject:	Population:	Influenced By:	
FMVSS 225 LOWER CHILD RESTRAINT ANCHORAGES	48	MFR	

Models:
2011 - 2011 MB II

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=11V597&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V164	CORP. MICRO BIRD, INC.	School Bus	
Subject:	Population:	Influenced By:	
WHEELCHAIR LIFT/OUTER ROLL STOP LATCHING ME	38	MFR	

Models:
2009 - 2011 G5

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V164&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V362	CORP. MICRO BIRD, INC.	School Bus	EQ12-008
Subject:	Population:	Influenced By:	
BUS ROOF ESCAPE HATCH/FMVSS 217	11	ODI	

Models:
2011 - 2012 G5

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V362&searchtype=quicksearch&summary=true



Monthly Recall Report

Division	Heavy Truck & Bus	Key Word
Veh. Type	School Bus	

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
11V573	DAIMLER TRUCKS NORTH AMERICA	School Bus		2011 - 2013 SAF-T-LINER C2
Subject:	Population:	Influenced By:		
C2 GRID HEATER RELAY WIRING	4700	MFR		
<p>To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p>http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=11V573&searchtype=quicksearch&summary=true</p>				

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
11V578	DAIMLER TRUCKS NORTH AMERICA	School Bus		2012 - 2012 SAF-T-LINER C2
Subject:	Population:	Influenced By:		
MALFUNCTIONING SIDE MARKER/DIRECTIONAL LIG	2800	MFR		
<p>To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p>http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=11V578&searchtype=quicksearch&summary=true</p>				

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
12V225	DAIMLER TRUCKS NORTH AMERICA	School Bus	PE11-030	2007 - 2011 MINOTOUR 2007 - 2011 SAF-T-LINER C2 2007 - 2011 SAF-T-LINER EF 2007 - 2011 SAF-T-LINER HDX
Subject:	Population:	Influenced By:		
WHEELCHAIR LIFT/OUTER ROLL STOP LATCHING ME	890	ODI		
<p>To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p>http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V225&searchtype=quicksearch&summary=true</p>				

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
12V226	DAIMLER TRUCKS NORTH AMERICA	School Bus	PE11-030	2010 - 2010 SAF-T-LINER HDX
Subject:	Population:	Influenced By:		
WHEELCHAIR LIFT/OUTER ROLL STOP LATCHING ME	100	ODI		
<p>To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p>http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V226&searchtype=quicksearch&summary=true</p>				

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
12V266	DAIMLER TRUCKS NORTH AMERICA	School Bus		2013 - 2013 SAF-T-LINER C2
Subject:	Population:	Influenced By:		
FRONT AXLE KNUCKLES	217	MFR		
<p>To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p>http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V266&searchtype=quicksearch&summary=true</p>				



Monthly Recall Report

Division	Heavy Truck & Bus	Key Word
Veh. Type	School Bus	

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V296	DAIMLER TRUCKS NORTH AMERICA	School Bus	
Subject:	Population:	Influenced By:	
EMERGENCY ROOF HATCHES/FMVSS 217	1312	MFR	

Models:

2010 - 2013	MINOTOUR
2010 - 2013	SAF-T-LINER C2
2010 - 2013	SAF-T-LINER EF
2010 - 2013	SAF-T-LINER HDX

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V296&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V358	DAIMLER TRUCKS NORTH AMERICA	School Bus	
Subject:	Population:	Influenced By:	
Front Axle Knuckles	2	MFR	

Models:

2013 - 2013	SAF-T-LINER C2
-------------	----------------

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V358&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
11V581	KINGMOR SUPPLY, INC.	School Bus	EQ11-002
Subject:	Population:	Influenced By:	
EVAPORATOR ASSEMBLIES/POSSIBLE FIRE/CARRIER	850	ODI	

Models:

2004 - 2012	CESB
2001 - 2011	FESB
2007 - 2012	RESB

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=11V581&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V059	NAVISTAR, INC	School Bus	
Subject:	Population:	Influenced By:	
SELF-LATCHING SEAT CUSHION/FMVSS 222	677	MFR	

Models:

2011 - 2012	BE
2011 - 2012	CE
2012 - 2012	RE

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V059&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V061	NAVISTAR, INC	School Bus	
Subject:	Population:	Influenced By:	
SERVICE BRAKES/TRACTION RELAY VALVE	920	MFR	

Models:

2012 - 2013	CE
2012 - 2013	RE

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V061&searchtype=quicksearch&summary=true



Monthly Recall Report

Division	Heavy Truck & Bus	Key Word
Veh. Type	School Bus	

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
12V258	NAVISTAR, INC	School Bus	PE11-030	2007 - 2011 CESB
Subject:	Population:	Influenced By:		
WHEELCHAIR LIFT/OUTER ROLL STOP LATCHING ME	4	ODI		
<p>To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p>http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V258&searchtype=quicksearch&summary=true</p>				

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
12V285	NAVISTAR, INC	School Bus		2012 - 2013 BE 2012 - 2013 CE 2012 - 2013 RE
Subject:	Population:	Influenced By:		
EMERGENCY ROOF HATCH/FMVSS 217	3491	MFR		
<p>To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p>http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V285&searchtype=quicksearch&summary=true</p>				

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
12V294	NAVISTAR, INC	School Bus		2011 - 2011 CE
Subject:	Population:	Influenced By:		
INTERIOR LOWER LINING JOINT/ FMVSS 221	158	MFR		
<p>To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p>http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V294&searchtype=quicksearch&summary=true</p>				

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
12V476	NAVISTAR, INC	School Bus	PE12-011	2005 - 2010 CESB 2006 - 2009 FESB 2006 - 2011 RESB
Subject:	Population:	Influenced By:		
High Pressure Oil Line May Leak Or Rupture	20902	ODI		
<p>To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p>http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V476&searchtype=quicksearch&summary=true</p>				

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
11V584	STARCRAFT BUS	School Bus		2008 - 2011 PRODIGY 2008 - 2011 QUEST
Subject:	Population:	Influenced By:		
REAR EMERGENCY EXIT DOOR HANDLE/FMVSS 217	1792	MFR		
<p>To see a summary of the recall click the Link below. To see complete details, click the "Document Search" button at the bottom of the web page that opens.</p> <p>http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=11V584&searchtype=quicksearch&summary=true</p>				



Monthly Recall Report

Division	Heavy Truck & Bus	Key Word
Veh. Type	School Bus	

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
11V585	STARCRAFT BUS	School Bus	
Subject:	Population:	Influenced By:	
SELF-LATCHING SEAT CUSHION/FMVSS 222	517	MFR	

Models:

2010 - 2011	PRODIGY
2010 - 2011	QUEST

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=11V585&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V089	STARCRAFT BUS	School Bus	
Subject:	Population:	Influenced By:	
SCHOOL BUS SEATS/FMVSS 222	22	MFR	

Models:

2010 - 2011	PRODIGY
2010 - 2011	QUEST

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V089&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
11V546	STARTRANS BUS CORPORATION	School Bus	
Subject:	Population:	Influenced By:	
CLEARANCE OF THE REAR DOOR EXIT/FMVSS 217	161	OVSC	

Models:

2007 - 2011	MFSAB
-------------	-------

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=11V546&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
11V572	STARTRANS BUS CORPORATION	School Bus	
Subject:	Population:	Influenced By:	
SEAT LATCH MECHANISM/FMVSS 222	69	MFR	

Models:

2010 - 2011	MFSAB
-------------	-------

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=11V572&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V185	STARTRANS BUS CORPORATION	School Bus	
Subject:	Population:	Influenced By:	
WHEELCHAIR LIFT/OUTER ROLL STOP LATCHING ME	4	MFR	

Models:

2009 - 2010	MFSAB
-------------	-------

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V185&searchtype=quicksearch&summary=true



Monthly Recall Report

Division	Heavy Truck & Bus	Key Word
Veh. Type	School Bus	

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V007	TRANS TECH BUS	School Bus	
Subject:	Population:	Influenced By:	
SELF-LATCHING SEAT CUSHION/FMVSS 222	333	MFR	

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www.odnhtsa.dot.gov/recalls/results.cfm?rcl_id=12V007&searchtype=quicksearch&summary=true

Models:

2011 - 2011	AG139SSSP500
2012 - 2012	DDW5+9159FRL SST
2010 - 2010	DW4+9139
2011 - 2011	DW4+9139SST
2010 - 2010	DW5+9159
2011 - 2011	DW5+9159CST
2010 - 2010	DW5+9159FRL
2011 - 2011	DW5+9159FRLS ST
2011 - 2011	DW5+9159SST
2010 - 2010	DW5139
2010 - 2010	DW5139FRL
2010 - 2010	DW6159
2010 - 2010	DW6159FRL
2011 - 2011	DW6159FRLSST
2009 - 2009	DW6159RL_SST
2011 - 2011	DW6159SST
2010 - 2010	DW6159-SST
2010 - 2010	DW7+9195
2010 - 2010	DW8195FRL
2011 - 2011	DWF6158
2011 - 2011	DWF6158FRL
2011 - 2011	DWF6158RLSST
2010 - 2010	ROADSTAR
2011 - 2011	SC139DSSA409
2011 - 2011	SC159DSFP600
2011 - 2011	SC159DSSA600
2010 - 2010	ST3 DEMO
2011 - 2011	ST3/DEMO
2010 - 2010	ST4
2010 - 2010	ST4-139



Monthly Recall Report

Division	Heavy Truck & Bus	Key Word
Veh. Type	School Bus	

2010 - 2010	ST5
2009 - 2009	ST5139
2010 - 2011	STH4
2010 - 2010	STH4+9
2011 - 2011	STH4139
2010 - 2010	STH4WC
2011 - 2011	STH5139
2010 - 2010	STH5FRL

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V090	TRANS TECH BUS	School Bus	
Subject:	Population:	Influenced By:	
SEAT BELT ASSEMBLY/FMVSS 210	11	MFR	

Models:
2011 - 2012 SST

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V090&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V172	TRANS TECH BUS	School Bus	
Subject:	Population:	Influenced By:	
WHEELCHAIR LIFT/OUTER ROLL STOP LATCHING ME	1	MFR	

Models:
2009 - 2009 DW5+9159FRL

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V172&searchtype=quicksearch&summary=true

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:
12V173	TRANS TECH BUS	School Bus	
Subject:	Population:	Influenced By:	
WHEELCHAIR LIFT/OUTER ROLL STOP LATCHING ME	77	MFR	

2008 - 2010	DW5+9159FRL
2009 - 2010	DW5159FRL
2008 - 2008	DW6+9166
2008 - 2010	DW6158FRL
2008 - 2010	DW6159FRL
2009 - 2009	DW7+9195FRL
2009 - 2009	DW8195FRL
2010 - 2010	STH4+9139

To see a summary of the recall click the Link below.
 To see complete details, click the "Document Search" button at the bottom of the web page that opens.
http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=12V173&searchtype=quicksearch&summary=true