



# Monthly Recall Report August, 2013

Division

Veh. Type

<b>Recall:</b>	<b>Manufacturer:</b>	<b>Vehicle Type:</b>	<b>NHTSA Inv #:</b>	<b>Models:</b>
<input type="text" value="13V308"/>	<input type="text" value="Navistar, Inc."/>	<input type="text" value="School Bus"/>	<input type="text" value="PE-222-130524"/>	<input type="text" value="2013 - 2014 AE"/>
<b>Subject:</b>	<b>Population:</b>		<b>Influenced By:</b>	<input type="text" value="2011 - 2014 BE"/>
<input type="text" value="Failed Knee Impact Testing/FMVSS 222"/>	<input type="text" value="22264"/>		<input type="text" value="OVSC"/>	<input type="text" value="2011 - 2014 CE"/>
<small>To see a summary of the recall click the Link below.</small>				
<small>To see complete details, click the "Document Search" button at the bottom of the web page that opens.</small>				
<input type="text" value="http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V308&amp;searchtype=quicksearch&amp;summary=true"/>				

<b>Recall:</b>	<b>Manufacturer:</b>	<b>Vehicle Type:</b>	<b>NHTSA Inv #:</b>	<b>Models:</b>
<input type="text" value="13V365"/>	<input type="text" value="Daimler Trucks North America"/>	<input type="text" value="School Bus"/>	<input type="text" value="PE13-006"/>	<input type="text" value="2013 - 2014 SAF-T-LINER EF"/>
<b>Subject:</b>	<b>Population:</b>		<b>Influenced By:</b>	<input type="text" value="2013 - 2014 SAF-T-LINER EFX"/>
<input type="text" value="Blocked Fuel Delivery Resulting in Stall"/>	<input type="text" value="175"/>		<input type="text" value="ODI"/>	<input type="text" value="2013 - 2014 SAF-T-LINER HDX"/>
<small>To see a summary of the recall click the Link below.</small>				
<small>To see complete details, click the "Document Search" button at the bottom of the web page that opens.</small>				
<input type="text" value="http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V365&amp;searchtype=quicksearch&amp;summary=true"/>				

<b>Recall:</b>	<b>Manufacturer:</b>	<b>Vehicle Type:</b>	<b>NHTSA Inv #:</b>	<b>Models:</b>
<input type="text" value="13V371"/>	<input type="text" value="Transportation Collaborative, Inc."/>	<input type="text" value="School Bus"/>	<input type="text"/>	<input type="text" value="2008 - 2009 DW6159RLSST"/>
<b>Subject:</b>	<b>Population:</b>		<b>Influenced By:</b>	<input type="text" value="2010 - 2010 SC159DSFP600"/>
<input type="text" value="Possible Toe Crush in Flip Seat"/>	<input type="text" value="100"/>		<input type="text" value="MFR"/>	
<small>To see a summary of the recall click the Link below.</small>				
<small>To see complete details, click the "Document Search" button at the bottom of the web page that opens.</small>				
<input type="text" value="http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V371&amp;searchtype=quicksearch&amp;summary=true"/>				

<b>Recall:</b>	<b>Manufacturer:</b>	<b>Vehicle Type:</b>	<b>NHTSA Inv #:</b>	<b>Models:</b>
<input type="text" value="13V374"/>	<input type="text" value="Lion Bus Inc."/>	<input type="text" value="School Bus"/>	<input type="text" value="PE-217-130729"/>	<input type="text" value="2013 - 2014 360"/>
<b>Subject:</b>	<b>Population:</b>		<b>Influenced By:</b>	
<input type="text" value="Decal Letter Size/FMVSS 217"/>	<input type="text" value="23"/>		<input type="text" value="OVSC"/>	
<small>To see a summary of the recall click the Link below.</small>				
<small>To see complete details, click the "Document Search" button at the bottom of the web page that opens.</small>				
<input type="text" value="http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V374&amp;searchtype=quicksearch&amp;summary=true"/>				

<b>Recall:</b>	<b>Manufacturer:</b>	<b>Vehicle Type:</b>	<b>NHTSA Inv #:</b>	<b>Models:</b>
<input type="text" value="13V375"/>	<input type="text" value="Lion Bus Inc."/>	<input type="text" value="School Bus"/>	<input type="text" value="OA-111-07261"/>	<input type="text" value="2013 - 2014 360"/>
<b>Subject:</b>	<b>Population:</b>		<b>Influenced By:</b>	
<input type="text" value="Mirror View/Missing decal/FMVSS 111"/>	<input type="text" value="23"/>		<input type="text" value="OVSC"/>	
<small>To see a summary of the recall click the Link below.</small>				
<small>To see complete details, click the "Document Search" button at the bottom of the web page that opens.</small>				
<input type="text" value="http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rcl_id=13V375&amp;searchtype=quicksearch&amp;summary=true"/>				



# Monthly Recall Report August, 2013

Division	Heavy Truck & Bus	Key Word
Veh. Type	School Bus	

Recall:	Manufacturer:	Vehicle Type:	NHTSA Inv #:	Models:
13V397	Navistar, Inc.	School Bus	PE222-1305-25	2013 - 2014 CE
Subject:	Population:	Influenced By:		2013 - 2013 RE
Seat Restraining Barrier/FMVSS 222	70	OVSC		

To see a summary of the recall click the Link below.  
To see complete details, click the "Document Search" button at the bottom of the web page that opens.

[http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rc\\_id=13V397&searchtype=quicksearch&summary=true](http://www-odi.nhtsa.dot.gov/recalls/results.cfm?rc_id=13V397&searchtype=quicksearch&summary=true)